

## HOW TO UPDATE DSP FIRMWARE ( VP8360 )



Please plug in the AC adapter to avoid low battery problem when updating.

### STEPS

1. Connect the device to your PC and save the file [FR0AK128.MMV](#) into the internal hard drive.
2. Remove the USB connection. Under stand-alone mode, find the [FR0AK128.MMV](#) file and press **OK** button to process the update.
3. It will ask “ Update to OA-1.2.8 “ , scroll to **YES** and press **OK** to enter next path.
4. The firmware upgrade will perform. It takes about 55 seconds.

Updating firmware...  
Please wait for 55 seconds  
xx% completed.

5. When the message “ Successfully Updated” appears , press OK button to power off the device.

Successfully Updated!  
  
Press OK to shutdown.

6. Power on the device again and go to OPTIONS / VERSION. You will find the firmware has been updated to version OA-1.2.8.

If you have any questions or comments, please feel free mail to [service@vosonic.com.tw](mailto:service@vosonic.com.tw)

VOSONIC Technology Corporation Homepage: [www.vosonic.com](http://www.vosonic.com)

7F1., No.159 ,Hsien-Cheng 9th Road, Chu-Pei City , Hsi-Chu, Taiwan

TEL:886 3 555 7745 FAX:886 3 555 0390